Cofts

03500.013052.1 (32.C13052D)

**PATENT** 

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

SHIGERU UEDA

Appln. No.: 09/985,710

Filed: November 6, 2001

For: IMAGE INPUT-OUTPUT APPARATUS

AND METHOD THEREFOR

Examiner: Jerome Grant, II

Group Art Unit: 2626

Patent No.: 6,947,166 B2

Issued: September 20, 2005

December 13, 2005

Certificate

DEC 1 5 2005

of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

### REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/14/2005 SZENDIE1 00000012 6947168

C1 FC:1811

100.00 OP

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentee Daniel S. Glueck

Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

DSG/lw

DC\_MAIN 224858v1

# Staple Here Only!

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

6,947,166 B2

DATED

September 20, 2005

INVENTOR(S) :

SHIGERU UEDA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 2

Line 14, "made" should read --make--.

#### COLUMN 5

Line 35, "ling" should read --line--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

\_\_\_\_\_\_\_

Form PTO 1050 (Rev. 3-82)

PATENT NO. 6,947,166 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  —

(Form#30) DWP/lw 224868v1

#### UNITED STATES PATENT AND TRADEMARK OFFICE

#### **CERTIFICATE OF CORRECTION**

PATENT NO.

6,947,166 B2

DATED

September 20, 2005

INVENTOR(S) :

SHIGERU UEDA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7

Line 13, "of,a" should read -- of a--.

Line 51, "on, flag" should read --on, indicating that a copying operation is in progress, the sequence returns to the step S20.

On the other hand, if the step S21 identifies that the copy mode flag is off or has been turned off, the sequence proceeds to a step S22 to display a message "remove sheets from the sorter" in the display unit 801 of the operational panel 102, and the sequence returns to the step S20 to await the elimination of the sheets from the sorter unit.

On the other hand, if the step S20 identifies the use of the sorter and that the bins of the necessary number are empty in the sorter at the printing, or identifies that the sorter is not used, the sequence proceeds to a step S25, in which the main controller 105 discriminates whether the copy mode flag is on. The copy mode flag is turned on when the copying operation is in progress, so that, if the printer engine 109 is in use and the copy mode flag is on, the sequence waits until the copy mode flag is turned off.

When the copy mode flag is turned off, the sequence proceeds to a step S26 for discriminating whether a scan start flag is on. As will be explained later, the scan start flag is set in case of the image input operation from the image input unit, and is turned on when the image input unit 101 completes the preparation for reading and starts the image reading operation. The steps S26 monitors that the scan start flag--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,947,166 B2

No. of add'l. copies @ 30¢ per page



# Staple Here Only! PRINTER'S TRIM LINE

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,947,166 B2

DATED

September 20, 2005

INVENTOR(S) :

SHIGERU UEDA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 2

Line 14, "made" should read --make--.

#### COLUMN 5

Line 35, "ling" should read --line--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,947,166 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) (Form#30) DWP/Iw 224868v1

### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,947,166 B2

DATED

September 20, 2005

INVENTOR(S)

SHIGERU UEDA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 7

Line 13, "of,a" should read -- of a--.

Line 51, "on, flag" should read --on, indicating that a copying operation is in progress, the sequence returns to the step S20.

On the other hand, if the step S21 identifies that the copy mode flag is off or has been turned off, the sequence proceeds to a step S22 to display a message "remove sheets from the sorter" in the display unit 801 of the operational panel 102, and the sequence returns to the step S20 to await the elimination of the sheets from the sorter unit.

On the other hand, if the step S20 identifies the use of the sorter and that the bins of the necessary number are empty in the sorter at the printing, or identifies that the sorter is not used, the sequence proceeds to a step S25, in which the main controller 105 discriminates whether the copy mode flag is on. The copy mode flag is turned on when the copying operation is in progress, so that, if the printer engine 109 is in use and the copy mode flag is on, the sequence waits until the copy mode flag is turned off.

When the copy mode flag is turned off, the sequence proceeds to a step S26 for discriminating whether a scan start flag is on. As will be explained later, the scan start flag is set in case of the image input operation from the image input unit, and is turned on when the image input unit 101 completes the preparation for reading and starts the image reading operation. The steps S26 monitors that the scan start flag--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

30 Rockefeller Plaza

Form PTO 1050 (Rev. 3-82) (Form#30) DWP/lw 224868v1 PATENT NO. 6,947,166 B2

No. of add'l. copies @ 30¢ per page

